COMMANDER, FIFTH COAST GUARD DISTRICT

AIDS TO NAVIGATION BRANCH

FEDERAL BUILDING, 431 CRAWFORD STREET

PORTSMOUTH, VIRGINIA 23704-5004 United States

PHONE: (757) 398-6486 FAX: (757) 398-6334 Coast Guard

OFFICE HOURS: 8:00 AM TO 4:00 PM (MONDAY-FRIDAY)

LOCAL NOTICE TO MARINERS

Coastal Waters from Little River Inlet, South Carolina to Shrewsbury River, New Jersey

WEEKLY SUPPLEMENT

BROADCAST NOTICE TO MARINERS

Navigation information having been of immediate concern to TO SUBSCRIBE, CHANGE ADDRESS OR BE the Mariner, and promulgated by the following broadcasts, has REMOVED FROM MAILING LIST CALL (757) 398-6367 been incorporated in this notice when still significant:

CCGD5 (D5)
 BNM 0094-97 TO 0107-97

GROUP PHILADELPHIA (PH)
 BNM 0153-97 TO 0158-97

GROUP CAPE MAY (CM)
 BNM 0133-97 TO 0152-97
 Electronic bulletin board

Service: (703) 313-5910
 ACTIVITIES BALTIMORE (BA) BNM 0228-97 TO 0260-97 4300 to 28.8 bps, 8 data bits, no parity, 1 stop bit

GROUP EASTERN SHORE (ES) BNM 0048-97 TO 0058-97 NIS watchstander, 24 hours a day: (703) 313-5900

• GROUP HAMPTON ROADS (HR) BNM 0294-97 TO 0324-97 Also available at the Internet Address:

GROUP CAPE HATTERAS (CH)
 BNM 0116-97 TO 0192-97
 HTTP://www.navcen.uscg.mil OR: ftp://ftp.navcen.uscg.mil
 GROUP FORT MACON (FM)
 RNM 0177 97 TO 0200 97

• GROUP FORT MACON (FM) BNM 0177-97 TO 0200-97

NOTES: (1) Unless otherwise indicated, missing and destroyed structures are presumed to be in the

immediate vicinity. Mariners should proceed with caution.

REFERENCES: Light List, Vol. II, Atlantic and Gulf Coasts, 1996 Edition (COMDTPUB P16502.2).

U.S. Coast Pilot 3, Atlantic Coast: Sandy Hook to Cape Henry (32nd Edition).

* * * * * * * * *

REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

* * * * * * * * *

USE OF THE LOCAL NOTICE TO MARINERS

The Weekly Supplemental editions contain only new information available subsequent to the issue date of the Monthly edition. To ensure having complete information concerning the waterways of the Fifth Coast Guard District, see Monthly edition 13/97, 1 April 1997.

* * * * * * * * *

I SPECIAL NOTICE

For information concerning the following items, see Monthly Edition Local Notice to Mariners 13/97, 1 April 1997.

- 1. INTENTIONAL ENCOUNTERS WITH WHALES PROHIBITED
- 2. DGPS INFORMATION
- 3. DISCREPANCY REPORTS OF THE MARINE DIFFERENTIAL GLOBAL POSITIONG SYSTEM (DGPS)
- 4. AVAILABILITY OF NAUTICAL CHART CORRECTION SUMMARIES
- 5. AVAILABILITY OF LIGHT LIST CORRECTION SUMMARIES
- 6. LATEST EDITIONS FOR NAUTICAL CHARTS AND PRICE GUIDE
- 7. NATIONAL OCEAN SERVICE CHARTS, PUBLICATIONS, AND TABLES
- 8. 1996 TIDE TABLES, TIDAL CURRENT TABLES
- 9. CAUTION TO BE USED IN RELIANCE UPON AIDS TO NAVIGATION
- 10. BRIDGE-TO-BRIDGE RADIOTELEPHONE PROCEDURES
- 11. PRIVATE AIDS TO NAVIGATION
- 12. NEW EDITION OF THE COAST PILOT

WATERWAYS ANALYSIS MANAGEMENT SYSTEM (WAMS) - MD - TANGIER SOUND - NANTICOKE RIVER

The Fifth Coast Guard District, Portsmouth Virginia is conducting a Waterways Analysis Management System (WAMS) survey of the Nanticoke Rivers. The WAMS system was developed to determine the navigational needs of the users of specific waterways, the adequacy of the navigational aids currently in place, and to solicit suggestions to improve navigation in these regions. The WAMS will be used in determining the future funding and resources for this region. Mariners are encouraged to contribute to this analysis by providing comments or suggestions relating to the navigational system, or waterway. Problems relating to the location of buoys, range lights, anchorages, repair response times, etc. in the Nanticke River, Nanticoke Cut, Nanticoke East Channel, Bivalve Channel, Board Creek may be addressed to:

Officer in Charge USCGC CHOCKBERRY(WLI 65304) 810 Norris Harbor Drive Crisfield, MD 21817-1656 Attn: BMC S. B. Hearn

Comments should be received before 1 August 1997

For more information concerning this WAMS project contact BMC S.B. Hearn at (410) 968-0971.

WATERWAYS ANALYSIS MANAGEMENT SYSTEM (WAMS) - MD - CHESAPEAKE BAY - SMITH ISLAND

The Fifth Coast Guard District, Portsmouth Virginia is conducting a Waterways Analysis Management System (WAMS) survey of the Smith Island. The WAMS system was developed to determine the navigational needs of the users of specific waterways, the adequacy of the navigational aids currently in place, and to solicit suggestions to improve navigation in these regions. The WAMS will be used in determining the future funding and resources for this region. Mariners are encouraged to contribute to this analysis by providing comments or suggestions relating to the navigational system, or waterway. Problems relating to the location of buoys, range lights, anchorages, repair response times, etc. in the Big Thorofare Channel, Tyler Creek and Tylerton Harbor, Sheep Pen Gut, Smith Island West side may addressed to:

Officer in Charge USCGC CHOCKBERRY(WLI 65304) 810 Norris Harbor Drive Crisfield, MD 21817-1656 Attn: BMC S. B. Hearn

Comments should be received before 1 August 1997

For more information concerning this WAMS project contact BMC S.B. Hearn at (410) 968-0971.

WATERWAYS ANALYSIS MANAGEMENT SYSTEM (WAMS) - MD - CHESAPEAKE BAY - MIDDLE CHESAPEAKE BAY TRIBUTARIES

The Fifth Coast Guard District, Portsmouth Virginia is conducting a Waterways Analysis Management System (WAMS) survey of the Middle Chesapeake Bay Tributaries.. The WAMS system was developed to determine the navigational needs of the users of specific waterways, the adequacy of the navigational aids currently in place, and to solicit suggestions to improve navigation in these regions. The WAMS will be used in determining the future funding and resources for this region. Mariners are encouraged to contribute to this analysis by providing comments or suggestions relating to the navigational system, or waterway. Problems relating to the location of buoys, range lights, anchorages, repair response times, etc. in the Knapps Narrows East Channel, Tilgham Island Harbor, Knapps Narrows West Channel, Harris Creek, Sharps Island may addressed to:

Officer in Charge USCGC CHOCKBERRY(WLI 65304) 810 Norris Harbor Drive Crisfield, MD 21817-1656 Attn: BMC S. B. Hearn

Comments should be received before 1 August 1997

For more information concerning this WAMS project contact BMC S.B. Hearn at (410) 968-0971.

INTENTIONAL ENCOUNTERS WITH WHALES PROHIBITED

From late fall to early spring, various species of whales, including the severely endangered right whale, may be encountered in the local offshore and inshore waters. Vessel operators are reminded to use caution around whales. Vessels are prohibited from approxaching within 500 yards of a right whale. Vessels must steer a course away from the right whale and immediatly leave the area. Intentional close approach to whales is prohibited and may result in a violation of federal or state law.

LNM 12(CG5) 25 MAR 1997

NEW JERSEY SEASONAL NAVIGATIONAL AIDS

All mariners are avised of this warning: THERE MAY BE A DELAY IN THE PLACEMENT OF THE STATE OF NEW JERSEY 1997 SEASONAL NAVIGATIONAL AIDS IN THE NAVIGATABLE WATERS OF THE STATE OF JEW JERSEY. MARINERS ARE URGE TO USE EXTREME CAUTION WHILE TANSITING THESE AREA. ANY QUESTION CONCERNING THE PLACEMENT OF THESE AIDS, (NAVIGATIONAL BUOY, STAKES, AND REGULATORY SLOW NO WAKE BUOYS) SHOULD BE DIRECTED TO NEW JERSEY. AIDS TO NAVIGATION DEPARTMENT. (609) 639-9541.

II DISCREPANCIES

The following is a list of Aid Discrepancies for the previous week. A summary of current discrepancies in aids to navigation is printed in the Monthly Edition Local Notice to Mariners 13/97, 1 April 1997.

LNR Name of Aid Status Chart BNM LNM

affected Ref. Ref.

30835 CAPE FEAR RIV CH LT 57 TRLB/DAMAGED 11537 0200FM

17/97

DISCREPANCIES CORRECTED

LNR	Name of Aid	Status	Chart	BNM Ref.		LNM Ref.			
affected Ref. Ref. ØØØØØØØØØØØØØØØØØØØØØØØØØØØØØØØØØØØØ									
07375 13955 03/97	CHESAPEAKE CH LB 52 UPPER YORK RVR DBN 21		IGHTED UILT/RECOVEF	12245 RED	0306HI 12243	R 16/97 0055HR			
27870 10/97	NORTHEAST RIV DBN 12	REB	UILT/RECOVEF	RED	12274	NONEBA			
28250 04/97	OLD HOUSE CH DBN 12	REB	UILT/RECOVEF	RED	12205	0028CH			
28735 12/97	HATTERAS IN LT 13	REB	UILT/RECOVEF	RED	11555	0100CH			
28860 12/97	ROLLINSON CH DBN 41	REB	UILT/RECOVEF	RED	11555	0105CH			
32060 NONE	CHICAMACOMICO CH DBN 4 CH 13/97		REBUILT/RE	ECOVERE	D	12204			
32590 34/96	BRANT IS WARN LT S	REB	UILT/RECOVEF	RED	11548	0343FM			
38195 08/97	GOOSE CK DBN 14	REB	UILT/RECOVEF	RED	11553	087FM			
38600 15/97	MOREHEAD CITY HBR JCT L	T MC	RELIGHTED)	11541	0169FM			
QQQQQQQQQQQQQQQQQQQQQQQQQQQQQQQQQQQQ									

ØØØØØØØØØØØØØØØØØ

NEW TEMPORARY CHANGES

The following aids have been temporarily changed from their advertised characteristics or positions. Their temporary positions can be obtained from Section IV of the Local Notice referenced in the right hand column. For a complete list of Temporary Changes see Monthly Edition Local Notice to Mariners 05/96, 4 February 1997.

LLNR 4865 (Se	Name of Aids Isle of Wight Bay DBN te Section IV)	12	Charts Status Discontinued		LNM affected 12211	d	Ref. 17/97
4865	Isle of Wight Bay B 12		shed ection IV)	12211		17/97	
29250	Bardens Inlet B 28	Discont (See Se	tinued ection IV)	11545		17/97	
	Morehead City Ch LB 2 e Section IV)	5	Relocated		11547		17/97
29470	Morehead City Ch LB 2	7	Relocated		11547		17/97
(See Section IV)							
29745	New River Ch DBN 15		tinued ection IV)	11542		17/97	

IV CHART CORRECTIONS

Corrective action affecting charts is contained in this section. Chart corrections are listed numerically by chart number. The correction listed pertains to that chart only. It is up to the mariner to decide what charts are to be corrected. The following example explains the individual elements of a typical correction.

Chart Chart Current Local	Edition	Last Local Notice	Horizontal	Source of
number edition Notice to Mariners	date	to Mariners	Datum Reference	Correction
/ /	/	/	/	/
(38/96)	12245 54 th ed. 02/03/96 LAST LNM 28/96) emp) HAMPTON ROADS location			(CG5)
Change: 76o17 01.4W	Fog signal	of Buoy PR to WHIS	STLE	37o00 06.2N
/	/		.	
Corrective and tenths) action	Object of o	corrective	Position (Degre	ees, minutes, seconds

The letter (M) immediately following the chart number indicates that the correction should be applied to the metric side of the chart only. (Temp) indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles (M).

11541 28th ed., 06/11/94 LAST LNM 17/97 NAD 83 17/97 (TEMP) ICW NEUSE RIV TO MYRTLE GROVE SD (CGD05) Delete New River Ch DBN 15, SG, in 34233'27.7"N 077221'21.8"W Morehead City CH LB 25 from (34²42'39.068"N, 76²41'40.05"W) to 34242'34.4"N 076241'31.6"W Morehead City CH LB 27 from (34²42'47.421"N, 76²41'51.811"W) to 34²42'49.1"N 076241'58.8"W 11541 28th ed., 06/11/94 LAST LNM 17/97 NAD 83 17/97 ICW NEUSE RIV TO MYRTLE GROVE SD (CGD05) Add Bogue Inlet By 19B, G C, in 34²40'03.6"N 077205'46.8"W Delete Broad Creek Wreck LT WR2 in 35²05'11.0"N 076232'53.0"W Bogue In B 5A from Relocate (3423839.585"N, 772617.316"W) to 34238'40.2"N 077206'04.1"W Bogue In B 10B from (34239'00.7"N, 7726'44.5"W) to 34²39'06.6"N 077²06'43.8"W Bogue In B 18A from (34239'34.9"N, 7726'07.9"W) to 34²39'27.9"N 077²06'15.5"W Bogue In B 19 from (34239'17.167"N, 7726'33.685"W) to 34239'36.8"N 077206'03.0"W Whittaker Creek DBN 3 from (3521'29.25"N, 76241'5.9"W) to 35201'30.1"N 076241'05.8"W 11542 14th ed., 07/03/93 LAST LNM 17/97 NAD 83 17/97 (TEMP) NEW RIVER (CGD05) Delete New River Ch DBN 15, SG, in 34233'27.7"N 077221'21.8"W 11543 20th ed., 07/11/92 LAST LNM 17/97 NAD 83 17/97 (TEMP) CAPE LOOKOUT TO NEW RIVER (CGD05) Relocate Morehead City CH LB 25 from $(34^242'39.068"N, 76^241'40.05"W)$ to 34242'34.4"N 076²41'31.6"W Morehead City CH LB 27 from

(34²42'47.421"N, 76²41'51.811"W) to 34242'49.1"N 076241'58.8"W 11543 20th ed., 07/11/92 LAST LNM 17/97 NAD 83 17/97 CAPE LOOKOUT TO NEW RIVER (CGD05) Add Bogue Inlet By 19B, G C, in 34240'03.6"N 077205'46.8"W Bogue In B 5A from Relocate (3423839.585"N, 772617.316"W) to 34238'40.2"N 077206'04.1"W Bogue In B 10B from (34239'00.7"N, 7726'44.5"W) to 34²39'06.6"N 077²06'43.8"W Bogue In Ch By 18A from (34239'34.9"N, 7726'07.9"W) to 34²39'27.9"N 077²06'15.5"W Bogue In B 19 from (34²39'17.167"N, 77²6'33.685"W) to 34239'36.8"N 077206'03.0"W 11544 34th ed., 05/11/96 LAST LNM 17/97 NAD 83 17/97 (TEMP) PORTSMOUTH ISLAND TO BEAUFORT: INCLUDING CAPE LOOKOUT SHOAL (CGD05) Barden Inlet By 28, R N, in 34239'47.6"N 076231'20.7"W 11545 57th ed., 01/18/97 LAST LNM 17/97 NAD 83 17/97 (TEMP) BEAUFORT INLET AND PART OF CORE SOUND (CGD05) Delete Barden Inlet By 28, R N, in 34239'47.6"N 076231'20.7"W Morhead City Ch LB 25 from Relocate (34242'39.068"N, 76241'40.05"W) to 34242'34.4"N 076²41'31.6"W Morehead City Ch LB 27 from (34²42'47.421"N, 76²41'51.811"W) to 34²42'49.1"N 076241'58.8"W 11547 31st ed., 08/12/95 LAST LNM 17/97 NAD 83 17/97 (TEMP) MOREHEAD CITY HARBOR (CGD05) Relocate Morehead City CH LB 25 from (34²42'39.068"N, 76²41'40.05"W) to 34242'34.4"N 076241'31.6"W Morehead City CH LB 27 from (34²42'47.421"N, 76²41'51.811"W) to 34242'49.1"N 076241'58.8"W 11548 34th ed., 02/05/94 LAST LNM 17/97 NAD 83 17/97

PAMLICO SOUND- WESTERNPART

(CGD05)

Delete Broad CreekWreck LT WR2 in 35²05'11.0"N

076232'53.0"W

Relocate Brant Is Warn DBN L from

(35²13'26.16"N, 76²23'33.48"W) to 35²13'24.0"N

076²23'32.7"W

Brant Is Warn DBN F from

(35²15'6.06''N, 76²26'25.26''W) to 35²15'06.2"N 076²26'26.2"W

Whittaker Creek DBN 3 from

(35²1'29.25"N, 76²41'5.9"W) to 35²01'30.1"N

076241'05.8"W

11550 26th ed., 07/08/95 LAST LNM 17/97 NAD 83 17/97

OCRACOKE INLET AND PART OF CORE SOUND

(CGD05)

Relocate Teaches Hole CH LB 22 from

(35²4'52''N, 76²0'56''W) to 35²04'53.0"N

076200'58.8"W

11552 17th ed., 10/31/92 LAST LNM 17/97 NAD 83 17/97

NEUSE RIVER AND UPPER PART OF BAY RIVER

(CGD05)

Relocate Whittaker Creek DBN 3 from

(35²1'29.25"N, 76²41'5.9"W) to 35²01'30.1"N

076²41'05.8"W

12204 33rd ed., 06/15/96 LAST LNM 17/97 NAD 83 17/97

CURRITUCK BEACH LIGHT TO WIMBLE SHOALS

(NOS)

Add Channel Tabulation Table from Enclosure 1.

Delete accurate landmark symbol and type: TR at 35²47'48.0"N

075233'01.0"W

accurate landmark symbol and type: TOWER (STROBE) at

35254'30.0"N 075240'24.0"W

Relocate Oregon Inlet Coast Guard Station symbol from

35²47'54.0"N 075²32'55.0"W to 35²46'06.0"N

075231'24.0"W

12205 24th ed., 06/15/96 LAST LNM 17/97 NAD 83 17/97

CAPE HENRY TO PAMLICO SOUND

(NOS)

Change Roanoke Sound depth legend to: 2 ¼ FT FOR WIDTH OF 100 FT 1996 in

35251'06.0"N 075236'36.0"W

Delete accurate landmark symbol and type: TOWER (STROBE) at

35254'30.0"N 075240'24.0"W

accurate landmark symbol, magenta circle and legend: R Bn 314

---.. at 35²47'48.0"N

075233'01.0"W

12210 34th ed., 12/28/96 LAST LNM 17/97 NAD 83 17/97

CHINCOTEAGUE INLET TO GREAT MACHIPONGO INLET

(CGD05)

Relocate Chincoteague In B 4A from

(37²51'40.823"N, 75²24'58.909"W) to 37²51'23.0"N

075225'01.0"W

Chincoteague In LB 5 from

(37²51'40.272"N, 75²25'1.254"W) to 37²51'23.5"N

075225'02.5"W

12211 37th ed., 10/29/94 LAST LNM 17/97 NAD 83 17/97

FENWICK ISLAND TO CHINCOTEAGUE INLET

(NOS)

Add black dotted lines, blue tint, and label: Obstn Fish Haven (auth

min depth 20 ft) joining 38²16'28.0"N 075²00'48.0"W

to 38²16'56.0"N 075²01'30.0"W to 38²15'44.0"N 075²02'48.0"W to 38²15'16.0"N 075²02'06.0"W

Delete obstn, fish haven, blue tint centered at 38216'00.0"N 075201'30.0"W

depth: 52 feet at 38216'02.0"N 075202'03.0"W

depth: 44 feet at 38215'48.0"N 075202'15.0"W

Relocate Chincoteague In B 4A from

(37²51'40.823"N, 75²24'58.909"W) to 37²51'23.0"N

075225'01.0"W

Chincoteague In LB 5 from

(37²51'40.272"N, 75²25'1.254"W) to 37²51'23.5"N

075225'02.5"W

12222 38th ed., 08/31/96 LAST LNM 17/97 NAD 83 17/97

CHESAPEAKE BAY CAPE CHARLES TO NORFOLK HARBOR (CGD05)

Add Back River South Channel DBN 2, TR, in

37²06'27.9"N 076²17'40.5"W

Pook Diver Couth Ch

Back River South Channel DBN 4, TR, in

37²06'23.4"N 076²17'38.5"W

Back River South Channel DBN 6, TR, in

37206'18.5"N 076217'39.1"W

Back River South Channel DBN 7, SG in

37206'15.0"N 076217'36.5"W

Back River South Channel DBN 8, TR, in

37206'13.0"N 076217'41.4"W

Back River South Channel DBN 9, SG, in

37206'07.8"N 076217'46.4"W

Back River South Channel DBN 10, TR, in

37206'02.3"N 076218'01.0"W

Delete Back River South Channel DBN 1 in

37²06'12.5"N 076²17'34.8"W

12238 34th ed., 01/21/95 LAST LNM 17/97 NAD 83

17/97

CHESAPEAKE BAY: MOBJACK BAY AND YORK RIVER ENTRANCE (CGD05) Add Back River South Channel DBN 2, TR, in 37206'27.9"N 076217'40.5"W Back River South Channel DBN 4, TR, in 37206'23.4"N 076217'38.5"W Back River South Channel DBN 6, TR, in 37206'18.5"N 076217'39.1"W Back River South Channel DBN 7, SG in 37206'15.0"N 076217'36.5"W Back River South Channel DBN 8, TR, in 37206'13.0"N 076217'41.4"W Back River South Channel DBN 9. SG. in 37206'07.8"N 076217'46.4"W Back River South Channel DBN 10, TR, in 37²06'02.3"N 076218'01.0"W Delete Back River South Channel DBN 1 in 37206'12.5"N 076217'34.8"W 12260 30th ed., 03/19/94 LAST LNM 17/97 NAD 83 17/97 CHESAPEAKE BAY: NORTHERN PART (CGD05) Craighill Channel Entrance RR LT height from 85ft to 88ft in Change 39207'03.6"N 076224'44.9"W 12263 46th ed., 09/21/96 LAST LNM 17/97 NAD 83 17/97 CHESAPEAKE BAY: COVE POINT TO SANDY POINT (CGD05) Matapeake N Breakwater LT 1 to Change Matapeake N Breakwater DBN 1, SG, in 38²57'23.0"N 076²21'25.0"W Sandy Pt Lt 5 to Sandy Pt DBN 5, SG, in 39²00'10.0"N 076²24'10.0"W Delete Brewer Creek Lt 2 in 38255'26.0"N 076231'36.0"W 12270 26th ed., 02/12/94 LAST LNM 17/97 NAD 83 17/97 CHESAPEAKE BAY: EASTERN BAY AND SOUTH RIVER (CGD05) Change Sandy Pt Lt 5 to Sandy Pt DBN 5, SG, in 39²00'10.0"N 076²24'10.0"W (NOS) Delete bascule bridge 38²59'36.0"N at 076²29'16.0"W and note: BASCULE BRIDGE HOR CL 75 FT (CLOSED) HOR CL 54FT (OPEN) VERT CL 12 FT Brewer Creek Lt 2 in 38255'26.0"N 076231'36.0"W 12273 48th ed., 10/22/94 LAST LNM 17/97 NAD 83 17/97 CHESAPEAKE BAY: SANDY POINT TO SUSQUEHANNA RIVER

(CGD05)

Change Craighill Channel Entrance RR LT height from 85ft to 88ft in 39207'03.6"N 076224'44.9"W

12278 65th ed., 09/28/96 LAST LNM 17/97 NAD 83 CHESAPEAKE BAY APP TO BALTIMORE

17/97

(CGD05)

Change Craighill Channel Entrance RR LT height from 85ft to 88ft in 39207'03.6"N 076224'44.9"W

12282 29th ed., 10/29/94 LAST LNM 17/97 NAD 83

17/97

CHESAPEAKE BAY: SEVERN AND MAGOTHY RIVERS (NOS)

Add Channel Tabulation Table from Enclosure 1.

Delete bascule bridge at 3825936.0N 07622916.0W

and note: BASCULE BRIDGE

HOR CL 75 FT (CLOSED) HOR CL 54FT (OPEN)

VERT CL 12 FT

12283 22nd ed., 04/15/95 LAST LNM 17/97 NAD 83 ANNAPOLIS HARBOR

17/97

(NOS)

Delete bascule bridge at 38259'36.0"N 076229'16.0"W

and note: BASCULE BRIDGE

HOR CL 75 FT (CLOSED) HOR CL 54FT (OPEN)

VERT CL 12 FT

12284 15th ed., 03/15/97 LAST LNM 17/97 NAD 83

17/97

PATUXENT RIVER: SOLOMONS ISLAND AND VICINITY (CGD05)

(CGD05)

(New edition due to changes in hydrography and various general changes.)

Add Patuxent River LT 11, showing Q G, 4 NM in

38220'27.7"N 076229'21.0"W

Delete Patuxent River DBN 11 IN

076229'16.8"W

Relocate Solomans Is App DBN 4 from

(38219'18.447"N, 76226'58.826"W) to

38²19'19.4"N

38²20'24.4"N

076²27'01.1"W

Solomons Is Hbr JCT LT from

(38219'18.447"N, 76227'10.826"W) to

38219'19.8"N 076227'14.2"W

Second Cove LT 1 from

(38²19'48.447"N, 76²28'22.829"W) to

38²19'48.0"N

076228'24.0"W

12316 26th ed., 06/18/94 LAST LNM 17/97 NAD 83

17/97

LITTLE EGG HARBOR TO CAPE MAY

(NOS)

Add Channel Tabulation Table from Enclosure 1.

12317 29th ed., 07/03/93 LAST LNM 17/97 NAD 83

17/97

CAPE MAY HARBOR

Add Channel Tabulation Table from Enclosure 1.

(NOS)

12324 27th ed., 06/11/94 LAST LNM 17/97 NAD 83 SANDY HOOK TO LITTLE EGG HARBOR (NOS) Add Channel Tabulation Table from Enclosure 1.

17/97

Light characteristics, FIR "10" to light dot at

39257'41.0"N 074205'05.0"W

(CGD05)

V SEASONAL CHANGES TO AIDS TO NAVIGATION

The following aids to navigation have been reset for the season:

LLNR	AID NAME	CHARTLLNR	AID N	AME	CHART			
4430.00	INDIAN RIVER CH	HANNEL JCT BY	12216	4520.00	INDIAN RIVER			
CHANNEL B	3112216							
4490.00	INDIAN RIVER CH	IANNEL BY 20	12216	4525.00	INDIAN RIVER			
CHANNEL B	3212216							
4495.00	INDIAN RIVER CH	IANNEL BY 22	12216	4530.00	INDIAN RIVER			
CHANNEL B	3412216							
4500.00	INDIAN RIVER CH	IANNEL BY 24	12216	4540.00	INDIAN RIVER			
CHANNEL B	3812216							
4505.00	INDIAN RIVER CH	IANNEL BY 26	12216	4545.00	INDIAN RIVER			
CHANNEL B	4012216							
4510.00	INDIAN RIVER CH	IANNEL BY 28	12216	4550.00	INDIAN RIVER			
CHANNEL B 4212216								
4515.00	INDIAN RIVER CH	IANNEL BY 30	12216					

VI ADVANCE NOTICE OF CHANGES TO AIDS TO NAVIGATION

DE - UPPER DELAWARE RIVER CHANNEL - TRENTON MARINE CENTER

The Delaware Valley Boat Racing Club, Inc, will be holding the "Thunder on the Delaware Dragboat Race" at the Trenton Marine Center in Trenton, NJ on 18 May 1997. Upper Delaware River Channel B 105 (LLNR 4340) and Upper Delaware River Channel B 106 (4345) at the west end of Trenton Marine Center will be removed prior to the event. All mariners are urged to transit the area with caution.

Charts: 12314 LNM 16 (CG5) 22 APR 97

DE - APPROACHES TO DELAWARE BAY TRAFFIC SEPARATION SCHEME (TSS)

On June 3, 1997 the Coast Guard will modify the Traffic Separation Scheme (TSS) in the Approaches to Delaware Bay. The TSS consists of a Precautionary Area, an Eastern approach, a Southeastern

approach, and a Two-Way Route for coastal traffic entering and departing Delaware Bay. Navigation safety, economic and environment consideration necessitate action to better separate large inbound vessels from coastal traffic transiting easterly and northerly along traditional New Jersey coastal routes. Enclosure 3 shows the future changes to the Traffic Separation Scheme. For further information contact LT Harvey at (757) 398-6285

Chart: 12214 LNM 09 (CG5) 04 MAR 1997

NC - CAPE HENRY TO PANLICO SOUND/ALBEMARLE SOUND

The following aid will be discontinued approximately May of 1997:

31645 ALBEMARLE SOUND DBN 4 36204'30."N 076212'54.0"W

The following aid will be established approximately May of 1997:

31645 ALBEMARLE SND LT 6AS 36200'44.0"N 076227'11.0"W

The following aid will be relocated approximately May of 1997:

31390 PASQUOTANK RIV ENT LT 36²09'18.0"N 075²58'24.0"W 37045

The following aids characteristic will be changed approximately May of 1997:

31510 PERQUIMANS RIV ENT LT 2P to show FL R 4s36204'30.0"N 076212'54.0"W

The following aids will be renamed approximately May of 1997:

```
31330 KITTY HAWK BAY LT 2 to KITTY HAWK BY LT 2KH 36201'11.0"N 075245'48.0"W
```

31515 PERQUIMANS RIV ENT DBN 3 to PERQUIMANS RIV ENT DBN 3P 36204'53.0"N 076217'33.1"W

```
31525 LITTLE RIV ENT DBN 1 to LITTLE RIV ENT DBN 1L 36205'54.6"N 076210'22.7"W
```

31585 SCUPPERNONG RIV CH ENT LT 1 to SCUPPERNONG RIV CH ENT LT 1SR 35256'58.1"N 076219'36.4"W

```
31630 ALBEMARLE SND LT 2 to ALBEMARLE SND LT 2AS 36203'08.2"N 076218'41.4"W
```

31670 ROANOKE RIV CH ENT LT 1 to ROANOKE RIV CH ENT LT 1RR 35257'26.6"N 076239'21.8"W

31790 CHOWAN RIV ENT LT 2 to CHOWAN RIV ENT LT 2CR 36²01'44.4"N 076²40'20.9"W

The following aids nominal range will be changed approximately May of 1997:

```
31390 PASQUOTANK RIV ENT LT to 11 nm 36209'18.0"N 075258'24.0"W
```

³¹³⁹⁵ PASQUOTANK RIV SLUE LT to PASQUOTANK RIV SLUE LT 36209'01.6"N 076201'17.7"W

³¹⁴⁸⁵ ALBEMARLE SND LT 1 to ALBEMARLE SND LT 1AS 36202'39.5"N 076204'30.6"W

³¹⁵¹⁰ PERQUIMANS RIV ENT LT 2 to PERQUIMANS RIV ENT LT 2P 36204'30.0"N 076212'54.0"W

³¹⁵⁷⁵ BULL BY DBN 2 to BULL BAY DBN 2BB 35256'42.6"N 076221'58.7"W

³¹⁶³² ALBEMARLE SND LT 4 to ALBEMARLE SND LT 4AS 36203'29.0"N 076222'43.0"W

³¹⁶³⁵ ALBEMARLE SND LT 5 to ALBEMARLE SND LT 5AS 36200'06.3"N 076223'32.2"W

³¹⁶⁵⁰ ALBEMARLE SND LT 6 to ALBEMARLE SND LT 8AS 35259'11.0"N 076235'15.0"W

³¹⁶⁵⁵ ALBEMARLE SND LT 7 to ALBEMARLE SND LT 9AS 35259'03.7"N 076235'21.0"W

³¹⁶⁶⁰ KENDRICK CK CH ENT LT 1 to KENDRICK CK CH ENT LT 1KC 35²56'33.1"N 076²36'42.3"W

³¹⁴⁸⁵ ALBEMARLE SND LT 1AS to 64nm 36202'39.5"N 076204'30.6"W

³¹⁵¹⁰ PERQUIMANS RIV ENT LT 2P to 54nm 36204'30.0"N 076212'54.0"W

³¹⁵²⁰ PERQUIMANS RIV ENT LT 5 to 4nm 36204'30.0"N 076212'54.0"W

Chart: 11553, 12205 LNM 10 (CG5) 11 Mar 1997

VII PROPOSED CHANGES TO AIDS TO NAVIGATION - None

VIII GENERAL

REGATTAS

The sponsor of a marine event must notify the Coast Guard if, (1) The event will involve more than 50 participating vessels or more than 200 spectator vessels; (2) The event will take place in or near a designated environmentally sensitive area (including a critical habitat of a threatened or endangered species), or other area of historic, cultural, archeological significance, including an area of significance to Native Americans; (3) The event will involve participating vessel traveling at speeds of greater than 30 miles per hour, (4) The event will cause participating vessels or spectator vessels to cross a designate shipping lane or otherwise block or cause substantial interference with navigation on a body of water, (5) The event could present a substantial threat to the safety of human life on navigable waters; or (6) The sponsor is requesting the use of Coast Guard resources or the issuance of a special local regulation.

Marine events meet one or more of the above criteria will be head at the following location on the date designated below. Unless otherwise noted, special navigation regulations have not been issued. In the interest of safety, however, all vessels operating in or passing through these area should proceed with caution and are request to cooperate in not distrupting these events. For more information about mariner events and special navigation regulations contact Boating Safety at 757-398-6204.

NORFOLK HARBOR, ELIZABETH RIVER, NORFOLK & PORTSMOUTH VA.

Special Local Regulations (33CFR100.501) will be in effect at various times from June 06 - 08, 1997 for the Norfolk Harborfest Celebration waterborn events, which consist of boat races, parades, demonstration, and fireworks displays. Contact Coast Guard Group Hampton Roads at (757) 483-8521 for further details.

CHESAPEAKE BAY, SANDY POINT TO KENT ISLAND MD.

Special Local Regulations (33CFR100.507) will be in effect from 8 AM - 2 PM on June 08, 1997 for the Great Chesapeake Bay Swim. Contact Coast Guard Activities Baltimore at (410) 576-2521 for further details.

For Special Local Regualations for Marine Events: Norforlk Harbor, Elizabeth River, Norfolk and Portsmouth VA see Enclosure 3.

For Special Local Regualations for Marine Events: Southern Branch Elizabeth River, Portsmouth VA see Enclosure 4.

ARTICLES

INTENTIONAL ENCOUNTERS WITH WHALES PROHIBITED

From late fall to early spring, various species of whales, including the severely endangered right whale, may be encountered in the local offshore and inshore waters. Vessel operators are reminded to use caution around whales. Vessels are prohibited from approaching within 500 yards of a right whale.

Vessels must steer a course away from the right whale and immediately leave the area. Intentional close approach to whales is prohibited and may result in a violation of federal or state law.

LNM 12 (CG5) 25 MAR 1997

PA - NJ - DE - DELAWARE RIVER - BRIDGESBURG CHNLHazNav

The Army Corps of Engineers dredge TITAN is conduction dredging operations outside the Bridesburg Channel on the New Jersey side of the Delaware River. The end of their dredge pipe that is on the rivers bottom is marked by a 3 foot yellow buoy with a flashing light. The sphere is barely visible during the day or night. Mariners are urged to transit the area with extreme caution.

Charts: 12311, 12312, 12314 LNM 17 (CG5) 29 APR 1997

NJ - AICW - PLEASANT CANAL - Bridge Information

The 10 AM bridge opening of the temporary operation schedule for the Veterans Memorial bridge, SR 88, Mile 3.0, and The Lovelandtown Bridge, SR 13, Mile 3.9, across Point Pleasant Canal at Point Pleasant, NJ, is canceled. The two bridges will resume opening for navigation as needed at 7 AM, 1 PM, 4 PM, and at 7 PM during the weekdays. After 7 PM weekdays and between 7 PM and 7 AM Monday, the bridges will resume opening on demand. The schedule will remain in effect until further notice..

Chart: 12323, 12324 LNM 17 (CG5) 29 APR 1997

PA - NJ - DE - DELAWARE RIVER - EAGLE PT RNGE - Dredging

The DREDGE #305 and its attendant plant are conducting dredging operations in the Eagle Point Range. The dredging operations will be conducted 24 hours a day, 7 days a week until approximately 01 May 1997. DREDGE #305 can be contacted on Channel 13 and 67 VHF-FM. Mariners transiting the area shall reduce speed and proceed with caution.

Chart: 12311, 12312 LNM 16 (CG5) 22 APR 1997

MD - POCOMOKE RIVER - SNOW HILL - Bridge Information

Due to mechanical failure/problems the Route 12 Bridge across the Pocomoke River, Mile 29.9, at Snow Hill, MD, will be closed to river traffic effective immediately until May 2, 1997. Mariners are urged to use extreme caution while transiting through the area

Charts: 12228, 12230 LNM 17 (CG5) 29 APR 1997

MD - CHESAPEAKE BAY - KNAPPS NARROWS - Bridge Information

The operating schedule for the drawbridge across Knapps Narrows, Mile 0.4 at Tilghman Island, Maryland is being temporarily amended due to pile driving for the construction of the new bridge adjacent to the existing bridge. Instead of opening on demand, the existing bridge will open every 15 minutes for the passage of vessels waiting to pass, 7 days a week, 24 hours a day beginning immediately until further notice. Mariners are urged to use extreme caution while transiting through the area.

Chart: 12266 LNM 17 (CG5) 29 APR 1997

VA - CHESAPEAKE BAY - RAPPAHANNOCK RIVER - Shoaling

Shoaling to bare has occurred between Rappahannock River B 57 (LLNR 15710) and Rappahannock River B 59 (LLNR 15715) in approximate position 38-09.6N 076-06.5W. Mariners are advised to exercise extreme caution when transiting the area.

Chart: 12211 LNM 17 (CG5) 29 APR 1997

VA - RUDEE INLET - Shoaling and Dredging

The City of Virginia Beach reports that Rudee Inlet has severe shoaling to a depth of less than four (4) feet in the navigational channel. Mariners are urged to avoid the inlet.

The dredge PULLEN will be conducting dredging operations in Rudee Inlet. The dredging operations will be conducted 24 hours a day, weather permitting starting 30 April 1997 until approximately 22 May 1997. The City of Virginia Beach is recommending that mariners do not use Rudee Inlet due to the severe shoaling at the inlet mouth.

Chart: 12205 LNM 17 (CG5) 29 APR 1997

VA - CHESAPEAKE BAY BRIDGE TUNNEL - Hazard to Navigation

The PCL Hardoway/Interbeton Company will be conducting construction on the southern side of the North Channel opening of the Chesapeake Bay Bridge Tunnel in approximate position 37-02.4N 076-04.3W. Mariners are urged top transit the area with caution.

Chart: 12222 LNM 15 (CG5) 15 APR 1997

VA - CHESAPEAKE BAY BRIDGE TUNNEL - Hazards to Navigation Update APRIL 7, 1997.

Sea and weather conditions permitting, the IB909 is scheduled to conduct steel erection at the North Channel bridge section of the Chesapeake Bay Bridge Tunnel. Structure and equipment could present a hazard to navigation. Mariners must navigate the channel with extreme caution. Unnecessary transiting of the area should be avoided. The contractor maintains radio watch on channels 16 and 67. VHF-FM

The following Marine Construction activities are ongoing at the tunnel:

- I. The Crane Barge 4600 is placing rip/rap and armor stone at Portal Island I.
- II. The Crane Barge 247 and the Crane Barge Mobro will be working in the vicinity of the North Channel area constructing foundations, columns and caps for the new bridge.
- III. The elevated work platforms IB909 and the Weeks 750 will be driving piles, caps and deck units at Trestle A. These operations will be conducted on a 24 hours basis. until May 1, 1997. At times the IB909 will obstruct the channel. The call letters are "P.E.V.B.". It maintains a radio watch on channels 16 and 67.
- IV. Three temporary morring piles have been driven at Trestle "A" at the following location: 37205'37.2N 75259'38.3"W affixed with a 3602 flashing yellow light
- VII. Rig and the Crane Barge Coen will be working in Fisherman's Inlet. The Coen Barge will be installing a fender system on the new bridge in Fisherman's Inlet. Upon completion of placement of rock Rig 23 will proceed to Trestle A.

The PCL/HARDAWAY/INTERBETON COMPANY has placed seven mooring piles in the North Channel area West of the Chesapeake Bay Bridge Tunnel. These piles will remain in place for up to 1 year and are lighted with a 360² flashing yellow light. The approximate position of the seven mooring piles are:

```
37<sup>2</sup>05'35.2N 075<sup>2</sup>59'45.3"W
                                           37205'37.8N 075259'36.2"W
37<sup>2</sup>05'35.8N 075<sup>2</sup>59'43.1"W
                                           37<sup>2</sup>05'38.5N 075<sup>2</sup>59'33.6"W
37<sup>2</sup>05'36.6N 075<sup>2</sup>59'45.3"W
                                           37205'39.3N 075259'16.2"W
37<sup>2</sup>05'37.2N 075<sup>2</sup>59'38.3"W
```

Mariners should be aware that all work is being performed on the West side of the existing Chesapeake Bay Bridge Tunnel. Floating equipment is secured by a six-point anchoring system with anchor cables extending up to 2000 feet in all directions from the equipment. Equipment is moved as necessary to structures and cables present extreme hazards to navigation. Mariners should avoid the construction zone if possible. Mariners should use extreme caution when transiting the area. Hazards to navigation are identifies by 360 flashing yellow lights.

The PCL/HARDAWAY/INTERBETON COMPANY has placed seven mooring piles in the North Channel area West of the Chesapeake Bay Bridge Tunnel. These piles will remain in place for up to 1 year and are lighted with a 360² flashing yellow light. The approximate position of the seven mooring piles are:

```
37<sup>2</sup>05'35.2N 075<sup>2</sup>59'45.3"W
                                     37205'37.8N 075259'36.2"W
37<sup>2</sup>05'35.8N 075<sup>2</sup>59'43.1"W
                                     37205'38.5N 075259'33.6"W
37<sup>2</sup>05'36.6N 075<sup>2</sup>59'45.3"W
                                     37<sup>2</sup>05'39.3N 075<sup>2</sup>59'16.2"W
37205'37.2N 075259'38.3"W
Chart: 12222 LNM 10 (CG5) 11 MAR 1997
```

VA - CHESAPEAKE BAY - ELIZABETH RIVER - Bridge Information

The Norfolk and Portsmouth Beltline Railroad Bridge, Mile 2.6 over the Southern Branch of the Elizabeth River in Chesapeak, VA will have a bridge tender on duty at all times. For further information contact Mr. Bill Brazier at (757) 398-6422.

Charts: 12245, 12253 LNM 17 (CG5) 29 APR 1997

VA - HAMPTON ROADS AND VICINITIY OF FORT WOOLHazNav

Tour boat MISS HAMPTON II reported a submerged object in the vicinity of Fort Wool in approximate position 36-59N 076-18W.

Chart: 12222, 12245 LNM 17 (CG5) 29 APR 1997

VA - HAMPTON - HAMPTON AND HERBERT'S CREEK - Dredging

The dredge MOBRO 1003, JAX V, and CAPTAIN WOODY will commence dredging operations in Hampton Creek and Herbert's Creek. The dredging operations will be conducted 24 hours a day, 7 days a week until approximately 15 June 1997. Mariners are urged to transit the area with extreme caution.

Charts: 12245, 12248 LNM 16 (CG5) 22 APR 1997

NC - VA - SEACOAST - Research Exercise

The Naval Research Laboratory (NRL) will be conducting a major research exercise off the Virginia/North Carolina coasts during May 1997. During this time, nine moorings are planned for deployment in local coastal waters. Seven of these moorings will consist of a bottom-mounted ADCP (Acoustic Doppler Current Profiler), attached to an anchor, with a surface current meter and temperature/salinity sensor. Next to the mooring will be an orange watch buoy for location identification at the surface. This buoy will be equipped with a yellow flashing beacon and a radar reflector. A diagram of this configuration is attached.

Two mooring will have additional optical collection instrumentation associated with them. One will have a single optical package located under the watch buoy. A diagram of this configuration is also provided. At on location, will plan to deploy a suite of additional optical sensors. This configuration is provided in the third diagram.

The planned locations for these moorings are (locations of more extensive optical buoy are indicated):

Virginia Coast: 36²38'N 075²52.5'W - water depth=33 ft.

36²30' line: 37²30'N 075²51.0'W - water depth = 20 ft. 36²30'N 075²50.4'W - water depth = 33 ft. 36²30'N 075²46.8'W - water depth = 33 ft.

 36^220 ' line: 37^220 'N $075^248.3$ 'W - water depth = 20 ft. 36^220 'N $075^247.5$ 'W - water depth = 35 ft. 36^220 'N $075^244.3$ 'W - water depth = 60 ft.

36²10' line: 36²10.'N 075²43.6'W - water depth = 35 ft. 36²10.'N 075²41.0'W - water depth = 64 ft.

These moorings will be deployed between the dates of 05 and 07 May and will be retrieved between 25 and 26 May. Please contact Dr. Weidemann (601) 688-5253 or Laurie Jugan at (601) 689-8441.

Chart: 12207 LNM 16 (CG5) 22 APR 1997

NC - TRENT RIVER - Bridge Information

The Trent River Bridge, US 70, crossing the Trent River, Mile 0.8, contractors will be working on the Fender system and will obstruct the channel from 6:00 AM April 21 through July 21, 1997. The navigation channel will be closed, alternate channels are available on both sides of the existing channel. Mariners are urged to transit the area with extreme caution.

Chart: 12323, 12324 LNM 17 (CG5) 29 APR 1997

NC - AICW - Bridge Information

The Hardaway company will be removing the fender system of the old swing bridge across the Atlantic Intracoastal Waterway at Hobucken, NC, beginning April 21 to April 25, from 7 AM to 5:30 PM each day. Navigation will be restricted from transiting through this area during the hours of work; However the waterway will be opened for the passage of vessels after 5:30 PM each day.

Chart: 11548 LNM 16 (CG5) 22 APR 1997

NC - NEW RIVER - Firing exercises

The Commanding General, Marine Corps Base, Camp Lejune, North Carolina, has advised that the area in the Atlantic Ocean between a point approximately 4.5 miles east of Bogue Inlet to a point approximately 10.0 miles southwest of New River Inlet, North Carolina, within the existing danger zone (depicted as 334.440) as shown on National Ocean Service Chart 11543, will be hazardous to navigation because of field firing exercises during the following periods:

NONE FOR THE PERIOD 5 - 11 MAY 97.

Firing to 3 miles seaward.

All navigation is urged to avoid the above area during the periods stated except for the Atlantic Intracoastal Waterway where mariners traveling through this area can expect a delay of about one hour during the above times. Range Control Boats, Marine Corps Base Camp Lejune, North Carolina monitor Channel 16 VHF-FM (156.8 MHz) and the working Channel 82 VHF-FM (161.725 MHz). The restricted areas in New River, as shown on National Ocean Service Chart 11542, will be closed to navigation because of firing exercises during the following periods:

Jacksonville Sector Sunrise to Sunset daily, 5 - 11 MAY 97.

Farnell Bay Sector
Traps Bay Sector
Stone Bay Sector
Stone Creek Sector
Grey Point Sector

Sunrise to Sunset daily, 5 - 11 MAY 97.
Sunrise to Sunset daily, 5 - 11 MAY 97.
12:01 AM to Midnight, 5 - 11 MAY 97.
12:01 AM to Midnight, 5 - 11 MAY 97.
12:01 AM to Midnight, 5 - 11 MAY 97.

The below listed times include a continuation of overhead fire of artillery across New River. Mariners may experience delays in transiting the New River in Grey Point sector.

NONE FOR THE PERIOD 5 - 11 MAY 97.

Ship operations consisting of landing craft, amphibious vehicles, and helicopters will be conducted in the Onslow Beach operating area and all sectors of New River from 12:01 AM to Midnight,

5 - 11 MAY 97.

Charts: 11542, 11543

IX LIGHT LIST CORRECTIONS for COMDTPUBP16502.2 Volume II 1996 Edition

(*)indicates change(s) in column indicated

- South Channel

12956

	(1) No. Remark	Name a	(3) and locati	(4) on	(5) Position		(7) Charac	(8) teristic	Height	Range	Structure
129	948	- South	Channel						SG on p	oile.	
•	Daybea *	acon 1	*	*	*	*	*	*	17/97		
•	12950 - South Daybeacon 2	Channel						TR on p	oile.		
						*		17/97			
•	12952 Daybea	- South	Channe						SG on I	oile.	
•	*	*	*	*	*	*	*	*	17/97		
		- South	Channel						TR on p	oile.	
•	Daybea *	*	*	*	*	*	*	*	17/97		
•	12955 Daybea • 17/		Channe							Remove	e from list.

TR on pile.

Daybeacon 6 17/97 12958 - South Channel TR on pile. Daybeacon 8 17/97 12960 - South Channel SG on pile. Daybeacon 9 17/97 14052 - Channel Buoy 2MB Red nun. 17/97 14055 - Channel Buoy 3MB Green can. 17/97 - Channel Buoy MB 14057 37 14.5 Red and white stripes. 76 15.4 • 17/97 - Channel Buoy 4MB 14060 Red nun. • 17/97

19620 - BREWER CREEK LIGHT 2

Remove from list.

17/97

29582 - Buoy 19B Green can.

* * * * * * * * * * * 17/97

K. H. WILLIAMS

VICE ADMIRAL, U. S. COAST GUARD

X ENCLOSURES

1. Tabulation of controlling depths for charts 12204, 12282, 12316, 12317, 12324.

2. Advance Notice of Delaware Bay Traffic Separation Scheme Changes.

- 3. Special Regulations for Marine Events: Norfolk Hbr, Elizabeth River, Norfolk and Portsmouth, VA.
- 4. Special Regulations for Marine Events: Southern Branch Elizabeth River, Portsmouth, VA.